

Keenan, John

From: Chaney, Connie <cchaney@omakwood.com>
Sent: Wednesday, November 27, 2013 11:35 AM
To: Olson, Gary
Cc: Keenan, John
Subject: FW: O2 Analyzer

From: Chaney, Connie
Sent: Wednesday, November 27, 2013 11:22 AM
To: 'Kris Ray'
Subject: RE: O2 Analyzer

The mill is not putting out that much smoke, I done an observation this morning, and it was 5 to 15 average. I had only 1 20 reading, everything else was lower than that.

I also done the Opacity Observations and they were all good.

From: Kris Ray [<mailto:Kris.Ray@colvilletribes.com>]
Sent: Wednesday, November 27, 2013 8:18 AM
To: Chaney, Connie
Cc: Gary Olson; keenan.john@epa.gov; Nicholson, Albert (AI); Gary Passmore
Subject: Re: O2 Analyzer

Why is the mill emitting a very high quantity of smoke
Sent from my iPhone

On Nov 27, 2013, at 7:55 AM, "Chaney, Connie" <cchaney@omakwood.com> wrote:

Hi Gary,

Due to circumstances beyond our control, we will not be able to install the O2 analyzer as scheduled. We will make arrangements, when the availability and cooperation with receiving the parts, to install as soon as possible. Any questions, please don't hesitate to call me at (509)322-7348.

Thank you for your understanding and patience.

Connie Chaney
Omak Wood Products
Environmental Mngr